

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters



Text Comments

| | | | |
|--------------|----------|----------|----------------|
| Camera Model | Flir b50 | Basement | Low insulation |
|--------------|----------|----------|----------------|

| | |
|------------|----------------------|
| Image Date | 1/7/2010 11:41:55 AM |
|------------|----------------------|

| | |
|------------|-------------|
| Image Name | IR_0019.jpg |
|------------|-------------|

| | |
|------------|------|
| Emissivity | 0.96 |
|------------|------|

| | |
|--------------------------------|---------|
| Reflected apparent temperature | 20.0 °C |
|--------------------------------|---------|

| | |
|-----------------|-------|
| Object Distance | 1.0 m |
|-----------------|-------|

Description

Living room wall, indicates missisng insulation

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters

| | | | |
|--------------------------------|----------------------|----------|----------------|
| Camera Model | Flir b50 | Basement | Low Insulation |
| Image Date | 1/7/2010 11:42:40 AM | | |
| Image Name | IR_0022.jpg | | |
| Emissivity | 0.90 | | |
| Reflected apparent temperature | 20.0 °C | | |
| Object Distance | 1.0 m | | |

Description

Living room, low insulation

What you see - drywal looks perfectly good

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters

| | | | |
|--------------------------------|----------------------|----------|----------------|
| Camera Model | Flir b50 | Basement | Low Insulation |
| Image Date | 1/7/2010 11:43:35 AM | | |
| Image Name | IR_0026.jpg | | |
| Emissivity | 0.90 | | |
| Reflected apparent temperature | 20.0 °C | | |
| Object Distance | 1.0 m | | |

Description

What you see -drywall looks perfectly good

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters

Text Comments

Camera Model Flir b50

Image Date 1/7/2010 12:11:37 PM

Image Name IR_0054.jpg

Emissivity 0.90

Reflected apparent temperature 20.0 °C

Object Distance 1.0 m

Description

Drywall and Ceiling looks perfectly good

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters

Text Comments

Camera Model Flir b50

Image Date 1/7/2010 12:16:35 PM

Image Name IR_0058.jpg

Emissivity 0.90

Reflected apparent temperature 20.0 °C

Object Distance 1.0 m

Description

Missing Insulation

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters



Text Comments

Camera Model Flir b50

Image Date 1/7/2010 11:53:24 AM

Image Name IR_0042.jpg

Emissivity 0.90

Reflected apparent temperature 20.0 °C

Object Distance 1.0 m

Description

Overheated wiring should be corrected by licensed electrician-Fire Hazard

Main Electrical Panel naked eye look OK

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters



Text Comments

Camera Model Flir b50

Image Date 1/7/2010 11:51:58 AM

Image Name IR_0038.jpg

Emissivity 0.90

Reflected apparent temperature 20.0 °C

Object Distance 1.0 m

Description

Overheated Wiring

Main Electrical Panel Naked Eye looks OK

Inspection Report

Report Date 1/7/2010

| | | | |
|---------------|-----------------------------|----------------|------------|
| Company | Home Proof Inspections Inc. | Customer | 123 ANYONE |
| Address | | Site Address | 123 |
| Thermographer | Adam Marzec | Contact Person | |





Image and Object Parameters

| | | | |
|--------------|----------|--|--------|
| Camera Model | Flir b50 | Living room ceiling missing insulation | Value0 |
|--------------|----------|--|--------|

| | |
|------------|----------------------|
| Image Date | 1/7/2010 12:09:41 PM |
|------------|----------------------|

| | |
|------------|-------------|
| Image Name | IR_0051.jpg |
|------------|-------------|

| | |
|------------|------|
| Emissivity | 0.90 |
|------------|------|

| | |
|--------------------------------|---------|
| Reflected apparent temperature | 20.0 °C |
|--------------------------------|---------|

| | |
|-----------------|-------|
| Object Distance | 1.0 m |
|-----------------|-------|

Text Comments

Description

| |
|--|
| Living room ceiling corner water leaking from roof |
|--|

| |
|--|
| What you see wall and ceiling looks good |
|--|